



LRQA INSPECTION IBERIA, S.A.

Certificate No. MAD9100026/1

Original Issued. 20 May 2011

Current Issued. 01 July 2022

## CERTIFICATE OF COMPLIANCE

**Name of Owner:** Medgaz S.A. Muelle de Poniente s/n, 04002 Almeria

**Name of Pipeline System:** Medgaz Pipeline

**Location:** From Beni Saf Compressor Station Algeria to the Onshore Pipeline Receiving Terminal – Almeria , Spain. This Certificate relates to both Offshore Pipeline and Onshore sections in Algeria and Spain.

**Description:** 24” Sub-sea Natural Gas Pipeline as described and with limits defined in Lloyd’s Register Certification Report ref. 112-06-CR-001 including the onshore and nearshore sections of the second future pipeline.

**Operational Limitations:** Pressure – Design 220 barg  
Temperature – Design -5°C to 50°C  
Service – Sales Quality Natural Gas

All above as defined in System Design and Performance Requirements – P2-PS-00025


**Certification Statement:** The Pipeline system described above has been verified to comply with the Medgaz Specifications by appropriate methods and levels of inspection, in accordance with the requirements stated in Contract number 112-06 between Lloyd’s Register España S.A. and MEDGAZ S.A. Work package 6 to DNV OSS-301 2000 level 2 Medium.

This Verification has been accepted by Lloyd’s Register España S.A. to be satisfactory for the risk to the integrity of the pipeline system and described in Verification Report No. 116-CR-001.


Due to the fact that Monitoring compliance with inspection and maintenance plan during Operational phase has been conducted by Lloyd’s Register España, .S.A (Now LRQA Inspection Iberia) with satisfactory results, and based on the 2021 annual review results described in Certification report P4-IP-REP-220630, renewal of certificate for 5 years was made on 01 July 2022.

**Verification Involvement:** Inspection and monitoring of manufacture of materials and equipment and also during construction and commissioning phase of the Pipeline from the PIG launcher in BSCS Algeria to the PIG receiver located in OPRT, Almeria , Spain

**Reference Documents:** DNV OS-F101 2000 - Submarine Pipeline Systems  
Offshore Pipeline Specification P2-PL-SPC-20413  
Onshore Pipeline Specification P2-PL-SPC-20409  
DNV OSS-301 2000 - Certification of Pipelines





Teresa Souto.  
Technical Manager – LRQA Inspection Iberia, S.A.



Jose Rivero:  
Operational Manager – LRQA Inspection Iberia, S.A.

“LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as ‘LRQA’. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.”

LRQA Inspection Iberia , S.A. Inscrita en el R. M. de Madrid, al Tomo 5218 general, 4358, de la Sec. 3.ª del Libro de Sociedades, folio 133; hoja n.º 41397, inscrip. 1.ª C.I.F. - A28591287 - Domicilio Social, C/Princesa 29, 1.º. 28008 Madrid.

	<b>LRQA INSPECTION IBERIA, S.A.</b>	<b>Certificate No.</b> MAD9100026/1  <b>Original Issued.</b> 20 May 2011 <b>Current Issued.</b> 01 July 2022
<b>CERTIFICATE OF COMPLIANCE</b>		
<b>1<sup>st</sup> Annual Assessment</b>		
<b>Date:</b> 31 July 2023 <b>Annual Review Report:</b> P4-IP-REP-230731 Rev0		
Teresa Souto. Technical Manager - LRQA Inspection Iberia, S.A.	Jose Rivero: Operations Manager - LRQA Inspection Iberia, S.A.	
		
<b>2<sup>nd</sup> Annual Assessment</b>		
<b>Date:</b> <b>Annual Review Report:</b>		
Teresa Souto. Technical Manager - LRQA Inspection Iberia, S.A.	Jose Rivero: Operations Manager - LRQA Inspection Iberia, S.A.	
<b>3<sup>rd</sup> Annual Assessment</b>		
<b>Date:</b> <b>Annual Review Report:</b>		
Teresa Souto. Technical Manager - LRQA Inspection Iberia, S.A.	Jose Rivero: Operations Manager - LRQA Inspection Iberia, S.A.	
<b>4<sup>th</sup> Annual Assessment</b>		
<b>Date:</b> <b>Annual Review Report:</b>		
Teresa Souto. Technical Manager - LRQA Inspection Iberia, S.A.	Jose Rivero: Operations Manager - LRQA Inspection Iberia, S.A.	