

LRQA INSPECTION IBERIA, S.A.

Certificate No. MAD9100026/2

First Issued. 20 May 2011 Current Issued. 01 July 2022

CERTIFICATE OF COMPLIANCE

Name of Owner: Medgaz S.A.

Name of Pipeline System: Beni Saf Compressor Station - BSCS

Location: Beni Saf Algeria

Description: Natural Gas Compressor Station including 4 Rolls Royce Turbo Compressors and associated equipment from connection with the Sonatrach Gas facilities to the connection to the PIG launcher from where Certification is included within Certificate No. MAD9100026/1 for the submarine pipeline.

Operational Limitations: Inlet Pressure – 70 barg Outlet 220 barg

Associated Services as defined in the System Design & Performance

Requirements document.

Service – Sales Quality Natural Gas

Certification Statement: The Pipeline Compressor Station described above has been verified to

comply with the Medgaz Specifications by appropriate methods and levels of inspection, in accordance with the requirements stated in Contract number 112-06 between Lloyd's Register España S.A. and MEDGAZ S.A. Work package 6 to ANSI B31.3 and Algerian Regulatory requirements.

work package 6 to ANSI B31.3 and Algerian Regulatory requirements.

This Verification has been accepted by Lloyd's Register España S.A. to be satisfactory for the risk to the integrity of the MEDGAZ pipeline system described above as described in Certification Report No. 112-06-CR-002.

Due to the fact that Monitoring compliance with inspection and maintenance plan during Operational phase has been conducted by Lloyd's Register España, .S.A (Now LRQA Inspection Iberia) with satisfactory results, and based on the 2021 annual review results described in Certification report P4-IP-REP-220630, renewal of certificate for 5 years

was made in 01 July 2022.

Verification Involvement: Inspection and monitoring of manufacture of materials, construction and

installation of equipment, commissioning and operational phase. Monitoring compliance with inspection and maintenance plan during

Operational phase.

Reference Documents: ANSI B.31.3 2003 – Gas Transpision and Distribution Piping Systems.

Teresa Souto.

Technical Manager - LRQA Inspection Iberia, S.A.

Jose Rivero:

Operations Manager - LRQA Inspection Iberia, S.A.



LRQA INSPECTION IBERIA, S.A.

Certificate No. MAD9100026/2

Original Issued. 20 May 2011 Current Issued. 01 July 2022

CERTIFICATE OF COMPLIANCE

1st Annual Assessment	
Date: 31 July 2023	
Annual Review Report: P4-IP-REP-230731 Rev0	
	Inna Dissana
Teresa Souto. Technical Manager - LRQA Inspection Iberia, S.A.	Jose Rivero: Operations Manager - LRQA Inspection Iberia, S.A.
lege	
2 nd Annual Assessment	
Date: Annual Review Report:	
Teresa Souto.	Jose Rivero:
Technical Manager - LRQA Inspection Iberia, S.A.	Operations Manager - LRQA Inspection Iberia, S.A.
3rd Annual Assessment	
Date: Annual Review Report:	
Teresa Souto.	Jose Rivero:
Technical Manager - LRQA Inspection Iberia, S.A.	Operations Manager - LRQA Inspection Iberia, S.A.
4th Annual Assessment	
Date:	
Annual Review Report:	
Teresa Souto.	Jose Rivero:
Technical Manager - LRQA Inspection Iberia, S.A.	Operations Manager - LRQA Inspection Iberia, S.A.

[&]quot;LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract."

LRQA Inspection Iberia, S.A. Inscrita en el R. M. de Madrid, al Tomo 5218 general, 4358, de la Sec. 3." del Libro de Sociedades, folio 133; hoja n.º 41397, inscrip. 1."

C.I.F. - A28591287 - Domicilio Social, C/Princesa 29, 1°. 28008 Madrid.